


SHT Instruction

CONTRAINDICATION:

SHT: Not suggested to fabricate 2 units continually missing bridge of posterior teeth.

SINTERING CURVE

Temperature



To achieve expected quality, the sintering curves must be followed.